



Tursdale Technical Services Ltd  
Unit N12B  
Tursdale Business Park  
Co. Durham  
DH6 5PG  
United Kingdom  
Phone: +44 ( 0 ) 191 377 3398  
Fax: +44 ( 0 ) 191 377 3357  
[info@tursdaletechnicalservices.co.uk](mailto:info@tursdaletechnicalservices.co.uk)  
<http://www.industrial-needs.com/>

## INSTRUCTION MANUAL PCE-1000



## CONTENTS

<b>1. Forewords</b> .....	<b>3</b>
1.1 History .....	3
1.2 Leeb Hardness Test (definition) .....	3
1.3 Notation of Leeb Hardness .....	3
<b>2. Features and applications</b> .....	<b>4</b>
2.1 Specifications .....	4
2.2 Features .....	4
2.3 Applications .....	4
<b>3. Designation of individual parts</b> .....	<b>5</b>
<b>4. Symbols and illustrations</b> .....	<b>5</b>
4.1 Symbols and illustrations of hardness scale .....	5
4.2 Symbols of materials .....	5
4.3 Measurement and conversion table .....	6
<b>5. Preparation before measuring</b> .....	<b>6</b>
5.1 Requirements for the sample .....	6
5.2 Requirements for the weight of the sample .....	6
5.3 Requirement for the surface hardened layer of the sample .....	7
5.4 Surface of the test sample should not be magnetic. ....	7
5.5 For test sample of curving surface with radius of curvature R. ....	7
5.6 Supporting the Samples during Testing .....	7
5.7 Samples with Curved Surfaces .....	7
<b>6. Operation</b> .....	<b>8</b>
6.1 Operation .....	8
6.2 Take measurement .....	9
6.3 View statistic value .....	9
<b>7. Calibration</b> .....	<b>10</b>
7.1 Intelligent calibration .....	10
7.2 Precise calibration .....	11
7.3 Default setting .....	11
<b>8. Maintenance and Repair</b> .....	<b>11</b>
8.1 Maintenance of the impact device .....	11
8.2 Charging battery .....	11
8.3 Fault Diagnosis .....	11

## 1. Forewords:

### 1.1 History

The Leeb measuring method was first brought into measurement technology in 1978. It is defined as the quotient of an impact body's rebound velocity over its impact velocity, multiplied by 1000. Harder materials produce a higher rebound velocity than softer materials. For a specific group of material (e.g. steel, aluminum, etc.), Leeb hardness value represents a direct relationship to its hardness properties. For ordinary metal, conversion curves of hardness HL versus other standard static hardness (HB, HV, HRC, etc.) are available, enabling you to convert HL into other hardness values.

### 1.2 Leeb Hardness Test (definition)

An impact body with a spherical test tip made of tungsten carbide is propelled against the sample surface by a spring force and then rebounds back. At a distance of 1mm from the sample surface, the impact and rebound velocity of the impact body are measured by the following method: A permanent magnet embedded in the impact body, when passing through the coil in its coil holder, induces in the coil an electric voltage proportional to the velocities of the magnet. Leeb hardness is expressed by the following formula:


$$HL = 1000 \times (VB/VA)$$

Where: HL is Leeb Hardness

VB is the rebound velocity of the impact body

VA is the impact velocity of the impact body

The voltage characteristic of output signal, when the impact body passes through the induction coil is illustrated in the following figure:



Voltage characteristic of output signal

A Leeb's Hardness Tester measures the hardness of sample material in terms of Hardness Leeb (HL), which can be converted into other Hardness units (Rockwell B and C, Vicker, Brinell and Shore D).

### 1.3 Notation of Leeb Hardness

When measuring the hardness of a sample material using the traditional static hardness testing method, a change of applied pressure will result in a change in the hardness reading.

For example: 720HLD≠720HLC

Because different converting curves are obtained from different impact devices, when converting hardness L into another hardness value the notation for the converted hardness value should include the impact device used.

## 2. Features and applications

### 2.1 Specifications

- Display: LCD with backlight
- Accuracy: +/-6HL at HL=800 (0.8%)
- Measuring range: 200-960L
- Conversion: HL-HRC-HRB-HB-HV-HSD
- Materials: 9 different common materials
- Wireless RS232 to PC and micro-printer (Plus)
- Memory: 99 data can be stored and re-readable
- Impact device: D
- Power on/off: Auto
- Power supply: DC 9V Ni-MH rechargeable battery
- Dimension: 100×60×33mm
- Weight: 150g

### 2.2 Features

- Rugged and modular design
- Palm size for narrow space
- High accuracy
- Take measurements on line with PC (Plus)
- Wireless RS232 (Plus)
- Wireless micro-printer (Plus)
- Automatic power on/off
- Recalibration allowed

### 2.3 Applications

- Hardness tests on installed machines or steel structures: e.g. on heavy and large work-piece or on permanently installed system parts.
- Rapid testing of multiple measuring areas for examination of hardness variations over larger regions.
- Measuring hardness for produced parts at production line.
- Identifying metallic material stored in a warehouse.
- Ineffectiveness analysis of permanent parts, pressure -vessel, turbo generator.


### 3. Designation of individual parts

#### Key M

- Mau
- Calculate data (AVE, MAX, MIN)
- Increment when adjusting

#### Key C

- Change setting
- Delete unrealistic values
- Decrement when adjusting
- Read stored data



### 4. Symbols and illustrations

#### 4.1 Symbols and illustrations of hardness scale

Symbols	Illustrations
LD	Leeb hardness value used with impact device D
HB	Brinell hardness value
HRB	Rockwell B hardness value
HRC	Rockwell C hardness value
HSD	Shore hardness value
HV	Vicker hardness value

#### 4.2 Symbols of materials

Symbol	Illustrations
1	Steel and cast steel
2	Cold work tool steel
3	Stainless steel and high temperature-resistant steel
4	Cast iron with lamellar graphite (grey cast iron GG)
5	Cast iron with spheroidal and nodular graphite (GGG)
6	Cast aluminium alloys
7	Copper-zinc alloys (brass)
8	Copper-alu / copper-tin alloys (bronze)
9	Wrought copper alloys, low alloyed

### 4.3 Measurement and conversion table

Range for measurement and conversion:

IMPACT DEVICE	D L D: 200-900				
	H R C	H R B	H B	H V	H S D
STEEL	20.0-67.9	59.6-99.5	80-647	80-940	32.5-99.5
CWT.ST	20.5-67.1			80-898	
ST.STEEL	19.6-62.4	46.5-101.7	85-655	85-802	
GC. IRON			93-334		
NC.IRON			131-387		
C.ALUM			30-159		
BRASS		13.5-95.3	40-173		
BRONZE			60-290		
COPPER			45-315		

## 5. Preparation before measuring

### 5.1 Requirements for the sample:

5.1.1 The surface temperature of sample should be less than 120 °C.

5.1.2 The samples must feature a metallic smooth, ground surface, in order to eliminate erroneous measurements brought about by coarse grinding or lathe scoring. The roughness of the finished surface should not exceed 2µm.

### 5.2 Requirements for the weight of the sample:

·For samples weighing over 5 kg and of compact shape, no support is needed.

Support, in such a manner that they do not bend or move by the impact force.

·Samples weighing less than 2 kg should be firmly coupled with a stable support weighing over 5 kg.

For coupling purposes,

- The coupling surface between the sample and base plate should be flat, plane parallel and ground.
- A thin proper layer of coupling paste is to be applied to the contact surface of the sample.
- The sample should be firmly pressed against the surface of the base plate by moving it with a circular motion.
- The direction of impact should be perpendicular to the coupling surface.

For the coupling operation, the following prerequisites must be fulfilled:

- The contact surface of the sample and the surface of the base plate must be flat, plane parallel and ground.
- The direction of the test impact must be perpendicular to the coupled surface.
- Minimum thickness of the sample for coupling (3mm).

Proper Coupling:

Proper coupling requires a little experience. Insufficiently coupled samples produce large variations of individual measurements, L-values which are too low and the operation is characterized by a rattling noise upon impact of the test tip.

Example for coupling a test piece with a base plate:



Application of the coupling paste  
(As thin as possible).

### 5.3 Requirement for the surface hardened layer of the sample:

Surface -hardened steels and especially case-hardened steels produce L-values which are too low when case-hardening depth is small because of their soft core. When measuring with impact device D the depth of the hardened layer should be no less than 0.8 mm.

### 5.4 Surface of the test sample should not be magnetic.

### 5.5 For test sample of curving surface with radius of curvature R less than 30 mm, a small support ring should be used.

### 5.6 Supporting the Samples during Testing

Type of impact device	Classification of samples		
	D	heavy more than 5 kg	medium-weight 2 – 5 kg

When measuring hardness with HARTIP 1500, the following has to be noticed: Despite the low mass of the impact body and low impact energy, a relatively large impact force of short duration is generated when the impact body hits the measuring surface. The max. impact force of impact device D is 900N.

For heavy samples of compact shape, no particular precautions are necessary.

Smaller and lighter samples or work pieces yield or flex under this force, producing L-values which are too small and of excessively large variation. Even with big or heavy work pieces it is possible for thin-wall regions or thinner protruding parts to yield upon impact. Depending on the frequency of the resilient yielding action, the measured L-value may be too small or too large. In many situations, potential problems can be checked in the following manner:

- Medium-weight samples and also heavier samples with protruding parts or thin walls should be placed on a solid support in such a manner that they do not move or flex during the test impact.
- Light-weight samples should be rigidly “coupled” with a non-yielding support such as a heavy base plate.


Clamping in a vice is of no value, since the samples become exposed to stress and because complete rigidity is never attained. As a rule, the measured L-values would be too small and show excessive variations.

### 5.7 Samples with Curved Surfaces

Impact testers only work properly, if the impact body has a certain position in the guide tube at the moment of impacting the test surface. In the normal position, automatically present when testing flat and convex-cylindrical samples (such as round samples), the spherical test tip is located exactly at the end of the guide tube.

However, when testing spherically or cylindrically shaped concave surfaces, the impact body remains further within the guide tube or protrudes further therefore. Thus, with such types of curved surfaces, it is to be observed that radii of curvature do not drop below the values indicated in the following Fig.

Curved surfaces should always be tested with the small support ring.



Impact device types D  $R_{min}=30mm$

For impact devices D, special support rings are available to accommodate smaller radii on convex or concave surface.

## 6. Operation





Diagram of operation:



### 6.1 Operation

6.1.1 Press key M for 3 seconds into item DIRE of the menu. Then by pressing key M in turn to enter into item MATE, CONV, AVER respectively. Finally come back to the mode of measurement.

6.1.2 After pressing key M for 3 seconds into item DIRE, press C in turn to change the impact direction.



6.1.3 After pressing key M into item MATE, press C in turn to change the materials setting.



M1: Steel/Cast Steel  
 M3: Stainless Steel  
 M5: Cast Iron nod.  
 M7: Brass

M2: Cold Work Tool Steel  
 M4: Grey Cast Iron  
 M6: Cast Alum. Alloys  
 M8: Bronzes



M9: Wrought Copper All.

6.1.4 After pressing key M into item CONV, press C to change the hardness scale (HLD-HRC-HRB-HB-HV-HSD).




6.1.5 After pressing key M into item AVER, press C in turn to select the average times from 0-3-4-5 and SAV. Selecting 0 means no mean values and SAV means memory is activated.



6.1.6 Press key M back to measuring mode, then LCD displays 0.

## 6.2 Take measurement



6.2.1 Press the release button on top of HARTIP 1500 to turn on the tester.

6.2.2 Insert the loading rod into the tube of impact device to push the impact body to depress the spring until the impact body is locked.

6.2.3 Place the tester against the surface of work piece.

**Please note:** the impact device must be firmly against the surface or you may get unsatisfied value.

6.2.4 Press the release button on top of the tester and take measurement. The measuring value will be displayed on LCD.

## 6.3 View statistic value

After test by certain average times, press M in turn. LCD displays mean value, max value and min value.

**Please note:** If a value is not realistic during measuring, press key C to delete it on LCD in order not to influence the calculating of average.

## 6.4 Memory

HARTIP 1500 can save 99 values in its memory and these stored values can be read after work.

#### 6.4.1 Activate memory

Press and hold key M for 3 seconds into menu of setup and press key M in turn to display AVER. Press key C to select SAV. (circle 0-3-4-5-SAV). Then press key M to come back measuring mode. At this moment, S00 will be displayed on left of LCD( if there are a few values in memory, it will be the ordinal number Sxx). Take measurements, all values will be stored automatically in memory.

#### 6.4.2 View stored values

Under measuring mode, press and hold key C for 3 seconds to enter into mode of viewing stored values. At same time, the ordinal number Sxx will be changed Rxx, press key M or C to recall stored values forwards and backwards. Then, press and hold key C for 3 seconds to come back measuring mode.

6.4.3 Clear memory: under the mode of viewing stored values, press and hold key M and C simultaneously for 3 seconds to delete all stored values.

## 7. Calibration

After a long period of use, especially for measuring harder materials, the ball tip of impact body will be worn which may lead the HARTIP 1500 have more or less error on accuracy. At this moment, HARTIP 1500 is designed to allow recalibration. The calibration can be made in two modes - intelligent and precise mode.

### 7.1 Intelligent calibration

7.1.1 Make sure the average time is to be set up 3 times


7.1.2 Take measurements on standard test block for 3 times

7.1.3 Press key M to display mean value of measurements.

7.1.4 Press and hold key C for 3 seconds, the mean value will be calculated automatically to standard value. At the same time, the LCD displays CAL at left.

7.1.5 Press and hold key M to confirm the calibration.

Diagram of calibration operation



## 7.2 Precise calibration

When you make intelligent calibration, if the calibrated value on LCD differs from standard value, please enter into precise calibration.

7.2.1 Make intelligent calibration step 1-4 procedures if the calibrated value differs from the standard value.

7.2.2 Press and hold key C for 3 seconds to enter into the mode of precise calibration. A sign of Adj will be displayed at left of LCD

7.2.3 Press key M or C to increase or decrease the value to be the standard value.

7.2.4 Press key M and C simultaneously to finish the calibration.

**Please note: 1. If the measurement error comes with in the range of accuracy specification, please do not make calibration easily.**

**2. Please make sure to recover factory setting first before make calibration each time.**

## 7.3 Default setting

After a long period of use, you may replace the impact body with a new one. Thus it needs to recover the factory setting (default).

7.3.1 Set up average by 3 times and take any measurements accordingly

7.3.2 Press key M to display mean value.

7.3.3 Press and hold key M and C simultaneously to recover factory setting.

## 8. Maintenance and Repair:

Do your best to avoid shock, heavy dust, damp, strong magnetic field, and oil stain.

### 8.1 Maintenance of the impact device

The devices do not require any particular care other than periodic cleaning of the impact body and the guide tube after performing approximately 1000-2000 tests. During cleaning, the following procedures need to be observed:

- Unscrew support ring and remove impact body from guide tube.
- Clean off any dirt and metallic dust from the impact body and the spherical test tip.
- Clean guide tube with the special brush provided.
- Do not apply oil to any parts for the impact device.

**8.2 Charging battery:** When a battery indicator displays on LCD which reminds you to charge the battery. However it is still possible to measure for some time. Please make sure to obtain additional or replacing battery from SADT. Otherwise it may cause Hartip 1500 to get un-accuracy value.

Insert the plug with battery charger into the socket on the right side of tester. Connect the battery charger with mains power to begin charging battery. It may take 12-15 hours to fully charge the battery.

**8.3 Fault Diagnosis:** If finding any abnormalities, please read our fault diagnosis first.

8.3.1 No impact occurs-impact body is not or improperly located in the impact device/impact body does not release or cannot be loaded.

8.3.2 Marked deviation of individual L-values or L-values constantly too low-measuring area inadequately prepared/the tested material is extremely inhomogeneous or porous/sample is insufficiently supported/sample exhibits large local hardness differences e.g. at the transition seam to the base material/impact direction has been

Changed between the individual impacts.

8.3.3 L-values at the standard test block constantly too low-impact device contaminated/spherical test tip cracked (e.g. due to impact against tungsten carbide)/support ring does not have rubber pad.

8.3.4 L-values at the standard test block constantly too high-spherical test tip flattened (impact against tungsten carbide, wear)/standard test block damaged or full of indentations.

8.3.5 If the test value displays ERRO on LCD, it means you make an improper operation.

In this direction will find a vision of the measurement technique:  
<http://www.industrial-needs.com/measuring-instruments.htm>

**NOTE:** "This instrument doesn't have ATEX protection, so it should not be used in potentially explosive atmospheres (powder, flammable gases)."