

User Manual

PCE-DPM 3 Dew Point Thermometer



User manuals in various languages (français, italiano, español, português, nederlands, türk, polski, pусский, 中文) can be found by using our product search on: www.pce-instruments.com

> Last change: 6 October 2020 v1.0



Contents

1	Safety notes	1
2	Specifications	2
3	Device description	3
3.1	Keyboard description	4
4	Measurement window	4
5	Main menu and symbols	5
5.1	Functions	5
5.2	Recording function	6
5.3	Display settings	7
5.4	Environmental parameters/ measurement settings	8
5.5	Further settings	9
6	Contact	10
7	Disposal	10



1 Safety notes

Please read this manual carefully and completely before you use the device for the first time. The device may only be used by qualified personnel and repaired by PCE Instruments personnel. Damage or injuries caused by non-observance of the manual are excluded from our liability and not covered by our warranty.

- The device must only be used as described in this instruction manual. If used otherwise, this can cause dangerous situations for the user and damage to the meter.
- The instrument may only be used if the environmental conditions (temperature, relative humidity, ...) are within the ranges stated in the technical specifications. Do not expose the device to extreme temperatures, direct sunlight, extreme humidity or moisture.
- Do not expose the device to shocks or strong vibrations.
- The case should only be opened by qualified PCE Instruments personnel.
- Never use the instrument when your hands are wet.
- You must not make any technical changes to the device.
- The appliance should only be cleaned with a damp cloth. Use only pH-neutral cleaner, no abrasives or solvents.
- The device must only be used with accessories from PCE Instruments or equivalent.
- Before each use, inspect the case for visible damage. If any damage is visible, do not
 use the device.
- Do not use the instrument in explosive atmospheres.
- The measurement range as stated in the specifications must not be exceeded under any circumstances.
- Non-observance of the safety notes can cause damage to the device and injuries to the user.

We do not assume liability for printing errors or any other mistakes in this manual.

We expressly point to our general guarantee terms which can be found in our general terms of business.

If you have any questions please contact PCE Instruments. The contact details can be found at the end of this manual.



Weight


2 Specifications						
Function	Measurement	Resol	ution	Accuracy at 20 °C / 68 °F		
Temperature	-10 60 °C	0.01 °C		-10 50 °C: ±0.3 °C		
Temperature	(+14 140 °F)	(0.018	-	(+14 122 °F: ±0.54 °F)		
Relative	0 100 %	0.01 %	6	<5 %: ±(0.025 % + 17.5 % of VAT)		
humidity				>5 %: ±(1 % + 5 % of VAT)		
				>15 %: ±(2 % + 3 % of VAT)		
Dew point	-50 30 °C	0.01 °	-	-40 20 °C: ±2 °C		
	(-58 86 °F)	(0.018		-5040 °C ±2.5 °C		
H2O	40 20.000 ppm	1 ppm		±(7.3 ppm + 8.3 %)		
The accuracy of the dew point is based on an ambient temperature of 16 25 °C / 61 77°F						
Further specifica						
Environmental co			-10 60 °C (14 140 °F)			
			0 20 bar (absolute)			
Response time at:				0 40 °C (-40 32 °F): 20 s [120 s]		
0.2 m/s, 1 bar, 20 °C (68 °F), 63 % RH [90				0 °C (-40 32 °F): 10 s [20 s]		
%].						
Data memory				for approx. 50.000 measuring points		
Adjustable storage rates			10 seconds			
			1, 5, 10, 20, minutes			
Adjustable recording time			1, 5, 12, 24, 48 hours			
File format			CSV			
Cable length			approx. 1.5 m			
Thread			G1/2 "			
Thread length				1.2 cm		
Probe length				5.2 cm		
Probe width				1		
Display				cm LCD		
Power supply - battery				3000 mAh		
Power supply – mains adaptor				Primary: 100 240 VAC, 0.25 A		
				dary: 5 VDC, 1 A		
Interface / mains connection				cro USB		

approx. 610 g



Device description 3


No.	Description				
1	Display				
3	Back key				
3	On/off switch,				
	hold key				
4	Arrow left key				
5	Interface 1 (no				
	function)				
6	Micro USB				
	interface				
7	Enter key				
8	Arrow up key				
9	Arrow right key				
10	Arrow down key				
11	Interface 2 for				
	connecting the				
	probe				
12	G1/2"				
	connection				
	thread				
13	Handle of the				
	probe				





3.1 Keyboard description

No.	Description	Function
1	Back key	Go back one menu level
2	On/off switch, hold key	Press and hold the key to switch the meter on and off. Press the key briefly once to freeze the display.
3	Arrow keys up and down	Navigating in the menu / changing parameters
4	Enter key	Confirming an entry / entering the menu
5	Arrow keys left and right	Navigating in the menu / changing parameters



4 Measurement window



Use the arrow keys to change the appearance of the measurement window. Two different versions are available.

In addition, you can hold the currently displayed values with the hold key and save them with the enter key (4) according to your preference. To exit hold mode, press the back key (1). Then press the back key (1) to view the saved values in the measurement window.



5 Main menu and symbols

Open the main menu by pressing the enter key.

Select the desired menu symbol with the left and right keys or return with the left function key.



5.1 Functions

In the "Functions" setting on the left, you can make changes to the alarm functions. Select the item "Setting" with the left or right key.

Alarm settings: Select between Td/f (dew point), T (temperature) or RH (relative humidity) with the enter key.

Setting the upper limit value:

Use the arrow down key to select the item "High Limit" and then press the enter key. Now you can enter a value with the up and down keys and confirm it by pressing the enter key again.

Setting the lower limit value:

Use the arrow down key to go to the item "Low Limit" and then press the enter key. Now you can enter a value with the up and down keys and confirm it by pressing the enter key again.

Alarm on/off:

Use the arrow keys to select On/Off and press the enter key to activate the alarm. If the measured value exceeds the high limit value or falls below the low limit value, the bell symbol appears at the top and an acoustic signal can be heard. Press the enter key again to deactivate the alarm.





Connect computer:

Select this item if you want to transfer the data to a computer. Do not leave this menu item during the transfer. The data is displayed in an Excel chart.

5.2 Recording function

To save the data of the measuring device, select the menu item "Recording" with the left or right arrow key. Now you can activate or deactivate data saving with the enter key.

Recording interval ("Record gap"): 10 s, 1 min, 5 min, 10 min, 20 min selectable

Record Time: 1 hour, 5 hours, 10 hours, 12 hours, 24 hours, 48 hours

The meter can save up to 32 files. One file contains 1000 data records. The capacity is therefore $32 \times 1000 = 32000$ records.

Note: If it is necessary to record for more than 6 hours, it is recommended to connect the instrument to a power supply to prevent power-related failure of the instrument.

The recorded data is saved in CSV format and can therefore be easily opened on a terminal device with Excel.

Attention: Make sure to save the data to your computer.




Display data: By means of the menu item "View DataFile", you can open and display the CSV data file via the device.





To view the saved data, press the right or left key. To view the next or previous data, press the up/down arrow keys to scroll through the data in steps of ten.



5.3 Display settings

In the display setting, you can select parameters. The temperature T is permanently selected and cannot be deselected. You can select or deselect all other parameters as you wish with the enter key.

Attention: You can select a maximum of two parameters. If you want to select a new parameter, you must first remove the other parameter.

The parameters can also be changed with the on/off key or the hold key. (For T d/f - dew point, for example, you can switch between Fahrenheit and Celsius).






5.4 Environmental parameters/ measurement settings

Can be selected to adjust the ambient pressure P of the probe and the molar mass of the gas measured in the probe.



5.4.1 Setting the probe pressure

Here you can set the pressure value P of the measured gas and the corresponding unit bara, barg, psia or psig. Change the value and select the unit by pressing the arrow up or down keys.





5.4.2 Adjust molar mass

The molar mass of air is 28.96 g/mol, and the molar mass of SF6 gas is 146.05 g/mol. When measuring SF6 gas, for example, ppmw M must be set to 146.05 g/mol. Change the value and select the unit by pressing the arrow up or down keys.



5.4.3 Cleaning

Select the "Cleaning" option and press the enter key. The probe will perform the cleaning and heat the sensor. The process takes about five to ten minutes.

5.5 Further settings

- 1 Language setting: Chinese and English.
- 2 Automatic power-off: off, 10 min, 15 min, 20 min, 25 min, 30 min
- 3 Brightness: Press the enter key to change the value. 10 different brightness levels can be selected.



Set the time and date, increase or decrease the number with the up or down keys and confirm your entry with the enter key.





The key sound can be enabled or disabled.

6 Contact

If you have any questions, suggestions or technical problems, please do not hesitate to contact us. You will find the relevant contact information at the end of this user manual.

7 Disposal

For the disposal of batteries in the EU, the 2006/66/EC directive of the European Parliament applies. Due to the contained pollutants, batteries must not be disposed of as household waste. They must be given to collection points designed for that purpose.

In order to comply with the EU directive 2012/19/EU we take our devices back. We either re-use them or give them to a recycling company which disposes of the devices in line with law.

For countries outside the EU, batteries and devices should be disposed of in accordance with your local waste regulations.

If you have any questions, please contact PCE Instruments.







PCE Instruments contact information

Germany

PCE Deutschland GmbH Im Langel 4 D-59872 Meschede Deutschland

Deutschland
Tel.: +49 (0) 2903 976 99 0
Fax: +49 (0) 2903 976 99 29
info@pce-instruments.com
www.pce-instruments.com/deutsch

United Kingdom PCE Instruments UK Ltd

Unit 11 Southpoint Business Park Ensign Way, Southampton Hampshire United Kingdom, SO31 4RF Tel: +44 (0) 2380 98703 0

Tel: +44 (0) 2380 98703 0 Fax: +44 (0) 2380 98703 9 info@pce-instruments.co.uk www.pce-instruments.com/english

The Netherlands

PCE Brookhuis B.V. Institutenweg 15 7521 PH Enschede Nederland Telefoon: +31 (0)53 737 01 92 info@pcebenelux.nl www.pce-instruments.com/dutch

United States of America

PCE Americas Inc.
1201 Jupiter Park Drive, Suite 8
Jupiter / Palm Beach
33458 FL
USA
Tel: +1 (561) 320-9162

Fax: +1 (561) 320-9176 info@pce-americas.com www.pce-instruments.com/us

France

PCE Instruments France EURL 23, rue de Strasbourg 67250 Soultz-Sous-Forets France Téléphone: +33 (0) 972 3537 17 Numéro de fax: +33 (0) 972 3537 18 info@pce-france.fr www.pce-instruments.com/french

Italy

PCE Italia s.r.l. Via Pesciatina 878 / B-Interno 6 55010 Loc. Gragnano Capannori (Lucca) Italia Telefono: +39 0583 975 114

Fax: +39 0583 974 824 info@pce-italia.it www.pce-instruments.com/italiano

China

PCE (Beijing) Technology Co., Limited 1519 Room, 6 Building Zhong Ang Times Plaza No. 9 Mentougou Road, Tou Gou District 102300 Beijing, China Tel: +86 (10) 8893 9660 info@pce-instruments.cn www.pce-instruments.cn

Spain

PCE Ibérica S.L.

Calle Mayor, 53
02500 Tobarra (Albacete)
España
Tel.: +34 967 543 548
Fax: +34 967 543 542
info@pce-iberica.es

www.pce-instruments.com/espanol

Turkey

PCE Teknik Cihazları Ltd.Şti. Halkalı Merkez Mah. Pehlivan Sok. No.6/C 34303 Küçükçekmece - İstanbul Türkiye

Tel: 0212 471 11 47 Faks: 0212 705 53 93 info@pce-cihazlari.com.tr www.pce-instruments.com/turkish

Hong Kong

Unit J, 21/F., COS Centre 56 Tsun Yip Street Kwun Tong Kowloon, Hong Kong Tel: +852-301-84912 jyi@pce-instruments.com www.pce-instruments.cn

PCE Instruments HK Ltd.