



# User Manual

PCE-PH 23 pH Meter



User manuals in various languages (français, italiano, español, português, nederlands, türk, polski, русский, 中文) can be found by using our product search on: [www.pce-instruments.com](http://www.pce-instruments.com)

Last change: 14 May 2020  
v1.0



## Contents

<b>1</b>	<b>Safety notes</b> .....	<b>1</b>
<b>2</b>	<b>Before first use</b> .....	<b>2</b>
2.1	Inserting / replacing the batteries .....	2
2.2	Soaking the electrode .....	2
<b>3</b>	<b>Device description</b> .....	<b>2</b>
3.1	Meter .....	2
3.2	Display .....	2
3.3	Operating modes of the meter .....	3
3.4	Key description .....	3
<b>4</b>	<b>Operation</b> .....	<b>4</b>
4.1	On / off .....	4
4.2	Set date and time .....	4
4.3	Select buffer solutions .....	4
4.4	pH value calibration .....	4
4.5	Measurement .....	5
4.6	HOLD mode .....	5
4.7	Saving readings .....	5
4.8	Viewing and deleting data .....	5
<b>5</b>	<b>Electrode replacement</b> .....	<b>5</b>
<b>6</b>	<b>Error messages</b> .....	<b>6</b>
<b>7</b>	<b>Specifications</b> .....	<b>6</b>
<b>8</b>	<b>Warranty</b> .....	<b>7</b>
<b>9</b>	<b>Disposal</b> .....	<b>7</b>

## 1 Safety notes

Please read this manual carefully and completely before you use the device for the first time. The device may only be used by qualified personnel and repaired by PCE Instruments personnel. Damage or injuries caused by non-observance of the manual are excluded from our liability and not covered by our warranty.

- The device must only be used as described in this instruction manual. If used otherwise, this can cause dangerous situations for the user and damage to the meter.
- The instrument may only be used if the environmental conditions (temperature, relative humidity, ...) are within the ranges stated in the technical specifications. Do not expose the device to extreme temperatures, direct sunlight, extreme humidity or moisture.
- Do not expose the device to shocks or strong vibrations.
- The case should only be opened by qualified PCE Instruments personnel.
- Never use the instrument when your hands are wet.
- You must not make any technical changes to the device.
- The appliance should only be cleaned with a damp cloth. Use only pH-neutral cleaner, no abrasives or solvents.
- The device must only be used with accessories from PCE Instruments or equivalent.
- Before each use, inspect the case for visible damage. If any damage is visible, do not use the device.
- Do not use the instrument in explosive atmospheres.
- The measurement range as stated in the specifications must not be exceeded under any circumstances.
- Non-observance of the safety notes can cause damage to the device and injuries to the user.

We do not assume liability for printing errors or any other mistakes in this manual.

We expressly point to our general guarantee terms which can be found in our general terms of business.

If you have any questions please contact PCE Instruments. The contact details can be found at the end of this manual.

## 2 Before first use

### 2.1 Inserting / replacing the batteries

Open the battery compartment cover and insert new batteries. Observe correct polarity. The unit can continue to operate for approximately 2 to 3 hours after the low battery indicator "BAT" appears on the display.

### 2.2 Soaking the electrode


The electrode must be soaked before first use or after storage. Remove the cover of the pH meter and soak the electrode in a potassium chloride solution with 3mol/l for 2 hours.

## 3 Device description


### 3.1 Meter

1. Battery compartment cover
2. LC display
3. Keypad
4. Electrode holder
5. Electrode and unit for automatic temperature compensation (ATC)

The electrode cap is not shown.



### 3.2 Display



- |  |                             |
|--|-----------------------------|
| 1. DATE  | Month-day-year (MM-DD-YY)   |
| 2. HOLD  | Display for Hold mode       |
| 3. MEASURE   | Display for measuring mode  |
| 4. BUF   | Selected buffer solutions   |
| 5. TIME  | 24 hours-minutes (HH:MM)    |
| 6. pH  | pH reading display          |
| 7. °C  | Temperature reading display |
| 8. Number of calibration point (1P/2P/3P) or type of calibration |                             |

**Note:** °C or °F is pre-set.

### 3.3 Operating modes of the meter

1. Measuring mode  
in the measuring mode
2. Calibration mode  
In calibration mode, the 1-point, 2-point or 3-point calibration is performed.
3. Hold mode  
In Hold mode, the measurement is interrupted and the currently measured value is held on the display.
4. Data retrieval mode  
In data retrieval mode, you can display measured values from the memory.
5. Date and time setting mode  
The date and time setting mode is used to correct the time and date.
6. Buffer selection mode for the calibration solutions  
In this mode, the buffer solution set for the calibration is selected: either 7.00 (pH values 7.00/4.01/10.01) or 6.86 (pH values 6.86/4.00/9.18).

### 3.4 Key description

Key	Operating mode	Duration of keystroke	Function
<b>HOLD</b>	Any but HOLD mode	2 s or more	Meter on/off
	Measuring mode	0 s	Holds current reading
	Hold mode	0 s	Back to measuring mode
	Date and time setting mode	0 s	Moves cursor to next data entry
<b>CAL</b>	Measuring mode	2 s	Jumps to calibration mode
	Measuring mode	10 s or more	Jumps to date and time setting mode
	Calibration mode	0 s	Leaves calibration mode
	Date and time setting mode	2 s	Leaves date and time setting mode
	Data retrieval mode	2 s	Clears memory and returns to measuring mode
<b>STORE</b>	Measuring mode	2 s	Saves current pH reading along with date and time
	Date and time setting mode	0 s	Increases current reading
	Data retrieval mode	2 s or more	Leaves data retrieval mode
	Buffer selection mode	2 s or more	Leaves buffer selection mode
<b>SCROLL</b>	Measuring mode	2 s	Starts data retrieval mode
	Measuring mode	5 s or more	Starts buffer selection mode
	Data retrieval mode	0 s	Scrolls through saved data
	Date and time setting mode	0 s	Decreases current reading
	Buffer selection mode	0 s	Selects a new buffer solution set

## 4 Operation

### 4.1 On / off

Press the HOLD key for 2 seconds or longer. The instrument will enter measurement mode. To switch off the meter, press the HOLD key again for 2 seconds. The instrument will turn off automatically when no key has been pressed for 10 minutes.

### 4.2 Set date and time

1. Press the "CAL" key for 10 seconds to start date and time setting mode
2. Press the "HOLD" key to select the date or time value
3. Press the "STORE" or "SCROLL" key to increase or decrease value
4. Press the "CAL" key for 2 seconds  
Exit and return to measuring mode

```

09-18-03 12:45

HOLD :NEXT SET
STORE :UP
SCROLL:DOWN
CAL  :2SEC EXIT
  
```

### 4.3 Select buffer solutions

1. Press "SCROLL" key for 5 seconds to start buffer selection mode
2. Press "SCROLL" key again to select the buffer solution set:  
7.00 for (7.00/4.01/10.01) or  
6.86 for (6.86/4.00/9.18)
3. Press "STORE" for 2 seconds  
Exit and return to measuring mode

```

09-18-03 12:45

CAL 6.86PH
      25.0 °C
SCROLL:SELECT
NEW BUFFER SET
SCROLL:2SEC EXIT
  
```

### 4.4 pH value calibration

1. Press the "CAL" key for 2...3 seconds to start calibration mode
2. Immerse the electrode in the 7.00 or 6.86 buffer solution. "WAIT" is displayed.
3. When the "WAIT" indicator disappears, the calibration for this value is finished.
4. Press "CAL" to complete the 1-point calibration or
5. repeat steps 2 and 3 with pH 4.01/4.00 or 10.01/9.18 for 2-point calibration
6. Press "CAL" to complete the 2-point calibration or
7. repeat step 5 for 3-point calibration
8. Automatic return to measuring mode

```

09-15-03 15:42
LAST CAL DATED
CAL 7.00PH
      25.0 °C
WAIT FOR END
POINT SENSING
BUF:7
  
```

**Note:** Clean the electrode with distilled water before each change of calibration solution. For accurate measurement results, it is recommended to perform pH calibration weekly and after each change of electrode.

## 4.5 Measurement


In measuring mode, immerse the instrument in the liquid to be tested.

Ensure that the electrode is immersed to a maximum of 2 mm below the electrode holder and that there are no solids in the water. These could influence the measurement result.

## 4.6 HOLD mode


1. When the pH reading is stable, press the "HOLD" key to hold it in the display
2. Press "HOLD" key to continue measurement

**Note:** In HOLD mode, the meter cannot be turned off.



## 4.7 Saving readings


1. Press the "STORE" key for 2...3 seconds in HOLD mode or measuring mode
2. "DATA SAVE" and "Mxx" indication on the display when data are stored in memory space Mxx
3. The instrument automatically returns to measuring mode.



**Note:** The instrument can store up to 50 measurements. When all memory spaces are occupied, the first memory space is overwritten first, then the following ones.

## 4.8 Viewing and deleting data

1. Press the "SCROLL" key for 2...3 seconds in measuring mode to call up the last saved measurement
2. Press the "SCROLL" key again to display the previously saved measurement
3. Press "STORE" for 2 seconds  
Exit and return to measuring mode or
4. Press "CAL" key for 2...3 seconds  
Clear memory completely and return to measuring mode



## 5 Electrode replacement

1. Unscrew electrode holder from the instrument
2. Remove old electrode from holder
3. Place new electrode in the holder
4. Place new electrode on the meter so that the holder fits into the electrode connections
5. Screw electrode holder onto the instrument
6. Soak electrode in 3M KCL for 2 hours
7. Calibrate the meter



## 6 Error messages

pH display	Temperature display	Mode	Possible causes
Any	"OVER"	Measurement	a) a) Temperature not within the range 0 ... 99.9 °C b) b) No temperature sensor c) c) Temperature sensor defective > Change the temperature of the liquid or > insert new temperature sensor
"OVER"	0 ... 99.9°C	Measurement	a) pH value not within the range 0 ... 14 b) Meter must be re-calibrated
"OVER"	0 ... 60°C	pH calibration	Offset value or slope value of the electrode outside the specified range > Use new buffer solutions > Change the electrode
Any	"OVER"	pH calibration	Temperature of buffer solution not 0...60 °C > Change temperature

## 7 Specifications

Measuring range pH measurement	0.00 ... 14.00 pH
Resolution pH measurement	0.01 pH
Measuring accuracy pH measurement	± 0.02 pH ± 1 digit
Buffer detection pH measurement	pH 7.00, 4.01, 10.01 or pH 6.86, 4.00, 9.18
Temperature compensation pH measurement	Automatically 0.0 ... 99.9°C / 32 ... 211.8°F
Buffer detection Temperature measuring range	0.0 ... 60°C / 32 ... 140°F
Offset detection pH electrode	± 90 mV at pH 7.00 ± 98.3 mV / -81.7 mV at pH 6.86
Slope pH electrode	± 30% at pH 4.00, 4.01, 9.18, and 10.01
input resistance	> 1012 Ω
<b>Technical Specification for Digital pH Meter PCE-PH 23: Temperature measurement</b>	
Measuring range temperature	0.0 ... 99.9°C / 32 ... 211.8°F
Resolution temperature	0.1°C / 0.18°F
Measuring accuracy temperature	± 0.3°C / 0.5°F
Temperature sensor	Thermistor, 10 kΩ at 25°C
Temperature unit	°C°F, default
<b>General technical specification for the Digital pH Meter PCE-PH 23</b>	
Power supply	4 x LR44
Lifespan batteries	200 hours
Operating temperature	0.0 ... 50.0°C / 32 ... 122°F
Display	98 x 64 pixels, graphic LCD
Casing	ABS, IP67
Weight	107 g / < 1 lb



## 8 Warranty

You can read our warranty terms in our General Business Terms which you can find here: <https://www.pce-instruments.com/english/terms>.

## 9 Disposal

For the disposal of batteries in the EU, the 2006/66/EC directive of the European Parliament applies. Due to the contained pollutants, batteries must not be disposed of as household waste. They must be given to collection points designed for that purpose.

In order to comply with the EU directive 2012/19/EU we take our devices back. We either re-use them or give them to a recycling company which disposes of the devices in line with law.

For countries outside the EU, batteries and devices should be disposed of in accordance with your local waste regulations.

If you have any questions, please contact PCE Instruments.





## PCE Instruments contact information

### Germany

PCE Deutschland GmbH  
Im Langel 4  
D-59872 Meschede  
Deutschland  
Tel.: +49 (0) 2903 976 99 0  
Fax: +49 (0) 2903 976 99 29  
info@pce-instruments.com  
www.pce-instruments.com/deutsch

### Germany

PCE Produktions- und  
Entwicklungsgesellschaft mbH  
Im Langel 26  
D-59872 Meschede  
Deutschland  
Tel.: +49 (0) 2903 976 99 471  
Fax: +49 (0) 2903 976 99 9971  
info@pce-instruments.com  
www.pce-instruments.com/deutsch

### The Netherlands

PCE Brookhuis B.V.  
Institutenweg 15  
7521 PH Enschede  
Nederland  
Telefoon: +31 (0)53 737 01 92  
info@pcebenelux.nl  
www.pce-instruments.com/dutch

### United States of America

PCE Americas Inc.  
711 Commerce Way suite 8  
Jupiter / Palm Beach  
33458 FL  
USA  
Tel: +1 (561) 320-9162  
Fax: +1 (561) 320-9176  
info@pce-americas.com  
www.pce-instruments.com/us

### France

PCE Instruments France EURL  
23, rue de Strasbourg  
67250 Soultz-Sous-Forêts  
France  
Téléphone: +33 (0) 972 3537 17  
Numéro de fax: +33 (0) 972 3537 18  
info@pce-france.fr  
www.pce-instruments.com/french

### United Kingdom

PCE Instruments UK Ltd  
Unit 11 Southpoint Business Park  
Ensign Way, Southampton  
Hampshire  
United Kingdom, SO31 4RF  
Tel: +44 (0) 2380 98703 0  
Fax: +44 (0) 2380 98703 9  
info@pce-instruments.co.uk  
www.pce-instruments.com/english

### China

PCE (Beijing) Technology Co., Limited  
1519 Room, 6 Building  
Zhong Ang Times Plaza  
No. 9 Mentougou Road, Tou Gou District  
102300 Beijing, China  
Tel: +86 (10) 8893 9660  
info@pce-instruments.cn  
www.pce-instruments.cn

### Turkey

PCE Teknik Cihazları Ltd.Şti.  
Halkalı Merkez Mah.  
Pehlivan Sok. No.6/C  
34303 Küçükçekmece - İstanbul  
Türkiye  
Tel: 0212 471 11 47  
Faks: 0212 705 53 93  
info@pce- cihazlari.com.tr  
www.pce-instruments.com/turkish

### Spain

PCE Ibérica S.L.  
Calle Mayor, 53  
02500 Tobarra (Albacete)  
España  
Tel. : +34 967 543 548  
Fax: +34 967 543 542  
info@pce-iberica.es  
www.pce-instruments.com/espanol

### Italy

PCE Italia s.r.l.  
Via Pesciatina 878 / B-Interno 6  
55010 Loc. Gragnano  
Capannori (Lucca)  
Italia  
Telefono: +39 0583 975 114  
Fax: +39 0583 974 824  
info@pce-italia.it  
www.pce-instruments.com/italiano

### Hong Kong

PCE Instruments HK Ltd.  
Unit J, 21/F., COS Centre  
56 Tsun Yip Street  
Kwun Tong  
Kowloon, Hong Kong  
Tel: +852-301-84912  
jyi@pce-instruments.com  
www.pce-instruments.cn