### Operation Manual

### Free Chlorine tester PCE-CHT 10



IA	BLE OF CO	NIENIS						
1.	Product Ove	rview	./	50"		2		
2.	<b>Precautions</b>	/	OLEA			2		
3	CONFIGURA	TION and LCI	INTROD	UCTION		3		
4.	Key Panel					3		
5.	Battery and	electrode ins				4		
6.	Measureme					5		
7.	Calibration	WIOGE		N II IV		5		
8.	Set up ····					6		
9.	<b>Parameters</b>					7		
10.	Package	/		- T		7		
11.	11. GENERAL INFÓRMATION							

#### 1. Product Overview

- Precise and easy operation, Comfortable holding, all functions operated in one hand.
- Large LCD with backlight, Multi-line display for easy reading, Auto-Power Off saves battery after
- 1\*1.5V AAA long battery life, User replaceable battery and high-impedance plane electrode
- Floats on water, IP67 rated
- Field throw measurement( Auto Lock Function)
- Use tri-electroded method measuring: faster and accurate, matching up to DPD results.



Floats on water IP67 rated



Large LCD with backlight Multi-line display for easy reading



Field throw measurement ( Auto Lock Function)



1\*1.5V AAA long battery life

#### 2. Precautions



Please wipe up the electorde with clean tissue or cloth before using: Do not throw or beat ,squash or twist the tester deliberately. Do not expose to the direct sunlight or put in high humidity or high temperature environment.

Do not use for long time under water

-2-

## 3. CONFIGURATION and LCD INTRODUCTION



S Data stabilized





Measurement mode

Auto Lock function

Auto Lock after data stabilized

In calibration

Sensor slope is between 50%-200%

Sensor slope is between 33.3%-50% or 200%-300%



# 4. Key panel

Short press: Short press means release the key once after pressing. (If there is no mark out below, default it as Short press)

Long press: Long press means press the key for 3 seconds and then release it Hold: Hold means not release the key and accelerate after a certain time. Not release the key until the value is set as needed.




Long press to Power ON/OFF Short press to ON/OFF backlight

Escape key when in calibration mode and setting up



Calibration key when in measurement mode Long press to enter into parameter browsing Increment values or scroll through the next options available





Confirm key


Press to unlock in Auto lock mode


# 5. Battery and Electrode installation

Unscrew the screw cap by following the arrow direction, slightly unplug the electrode, install the battery(pay attention to the anode and cathode of the electrode).

Then install back the electrode and the screw cap.

Low battery prompt is at the top of the screen when battery power is low.( You can refer to the LCD INTRODUCTION). Please change the same model battery.





### 6. Measurement Mode

to power up. The tester will then enter into measurement mode. The measurement icon will twinkle if the data is unstabilized. Once stabilized, the top stabilized icon will be displayed then.

### 7. Calibration Mode

In measurement mode, press\* (CAL) " to enter calibration mode. Prompting icons will be displayed on the screen. The PCE-CHT 10 adopts DPD comparative way to calibrate, which also requires constant flow rate.











Dip the electrode into the test solution, the stabilized icon will be displayed at the top of the screen once the data stabilized. Press " (ENT) " to confirm.

In Pic2, the screen will show STD. The standard value for calibration is at the below. Press " $\left(\frac{\text{CAL}}{\blacktriangle}\right)$ " and " $\left(\frac{\text{SET}}{\blacktriangledown}\right)$ " to adjust the value as the standard and press " $\left(\frac{\text{ENT}}{\bullet}\right)$ " to confirm. The offset value will be shown after calibration (in Pic3). If wrong, the "ERR" will be displayed. In Pic4, zero point calibration. Press " $\left( \text{ENT} \right)$ " to confirm and view the offset value. In Pic5, you can also directly press" (1) " to skip calibration and go back to

Long press\* "to browse the calibrated parameters in measurement mode. Press" (CAL) " and " (SET) " to check the zero offset and the actual measurement value.






-5-

## 8. Set up

In measurement mode, press "  $\underbrace{\frac{\text{SET}}{\Psi}}$ " to enter SET UP. Corresponding icons will be displayed. You can press "  $\underbrace{\frac{\text{SET}}{\Psi}}$ " and "  $\underbrace{\frac{\text{SET}}{\Psi}}$ " to select the menu and then press "  $\underbrace{\text{ENT}}$ " to confirm. Press " CAL" " or " SET" " to set up and confirm by press " (ENT) ". You can also press " to back to measurement mode.

The Set up menu as follow:



P01: Unit of the temperature. You can select between °C and °F.

P02: Auto Lock, You can select "ON" or "OFF" to auto lock the data once stabilized.

P03: Factory defaults. You can select to revert to factory defaults

-6-

### 9. Specification

Range	0 -10.00 mg/L
Resolution	0.01 mg/L
Accuracy	±2% F.S.
Temp. Range	0 - 100.0 °C / 32 - 212 °F
Working Temperature	0 - 60.0 °C / 32 - 140 °F
Calibration Point	2 points
LCD	20* 30 mm multi-line crystal display
Lock	Auto / Manual
Electrode	C\$5930
Auto backlight off	1 minutes
Auto power off	20 minutes without key be pressed
Power	1x1.5V AAA battery
Dimensions	(H×W×D) 185×40×48 mm
Weight	95g
Protection	IP67

### 10. Package

1 x PCE-CHT 10 chlorine Tester 1 x 1.5V AAA battery 1 x instruction manual

### 11. GENERAL INFORMATION

#### Contact

If you have any questions, suggestions or technical problems, please do not hesitate to contact us. You will find the relevant contact information at the end of this user manual.

For the disposal of batteries in the EU, the 2006/66/EC directive of the European Parliament applies. Due to the contained pollutants, batteries must not be disposed of as household waste. They must be given to collection points designed for that purpose.

In order to comply with the EU directive 2012/19/EU we take our devices back. We either re-use them or give them to a recycling company which disposes of the devices in line with law.

For countries outside the EU, batteries and devices should be disposed of in accordance with your

-8-

If you have any questions, please contact PCE Instruments.







-7-

#### PCE Instruments contact information

#### Germany

PCE Deutschland GmbH

Im Langel 26
D-59872 Meschede
Deutschland
Tel.: +49 (0) 2903 976 99 0
Fax: +49 (0) 2903 976 99 29
info@pce-instruments.com
www.pce-instruments.com/deutsch

#### United Kingdom

PCE Instruments UK Ltd
Trafford House
Chester Rd, Old Trafford
Manchester M32 0RS
United Kingdom
Tel: +44 (0) 161 464902 0
Fax: +44 (0) 161 464902 9
info@pce-instruments.co.uk
www.pce-instruments.com/english

#### The Netherlands

PCE Brookhuis B.V.
Institutenweg 15
7521 PH Enschede
Nederland
Telefoon: +31 (0)53 737 01 92
info@pcebenelux.nl
www.pce-instruments.com/dutch

#### France

PCE Instruments France EURL
23, rue de Strasbourg
67250 Soultz-Sous-Forets
France
Téléphone: +33 (0) 972 3537 17
Numéro de fax: +33 (0) 972 3537 18
info@pce-france.fr
www.pce-instruments.com/french

#### Italy

PCE Italia s.r.l.
Via Pesciatina 878 / B-Interno 6
55010 Loc. Gragnano
Capannori (Lucca)
Italia
Telefono: +39 0583 975 114
Fax: +39 0583 974 824
info@pce.italia.it
www.pce.instruments.com/italiano

#### United States of America

PCE Americas Inc.
1201 Jupiter Park Drive, Suite 8
Jupiter / Palm Beach
33458 FL
USA
Tel: +1 (561) 320-9162
Fax: +1 (561) 320-9176

info@pce-americas.com www.pce-instruments.com/us

#### Spain

PCE Ibérica S.L.
Calle Mula, 8
02500 Tobarra (Albacete)
España
Tel.: +34 967 543 548
Fax: +34 967 543 542
info@pce-iberica.es
www.pce-instruments.com/espanol

#### Turkey

PCE Teknik Cihazları Ltd Şti.
Halkalı Merkez Mah.
Pehlivan Sok. No.6/C
34303 Küçükçekmece - İstanbul
Türkiye
Tel: 0212 471 11 47
Faks: 0212 705 53 93
info@pce-cihazlari.com.tr
www.pce-instruments.com/turkish

#### Denmark

PCE Instruments Denmark ApS Birk Centerpark 40 7400 Herning Denmark Tel.: +45 70 30 53 08 kontakt@pce-instruments.com www.pce-instruments.com/dansk