



PCE Americas Inc.
1201 Jupiter Park Drive
Suite 8
Jupiter
FL-33458
USA
From outside US: +1
Tel: (561) 320-9162
Fax: (561) 320-9176
info@pce-americas.com

PCE Instruments UK Ltd.
Unit 11
Southpoint Business Park
Ensign way
Hampshire / Southampton
United Kingdom, SO31 4RF
From outside UK: +44
Tel: (0) 2380 98703 0
Fax: (0) 2380 98703 9
info@pce-instruments.co.uk

www.pce-instruments.com/english
www.pce-instruments.com

Manual

PCE-GM 100 Gloss Meter Instructions



1. Brief Introduction.....	3
2. Applications	3
3. Instrument Characteristics	3
4. Technology parameter.....	3
5. Display instructions.....	3
6. Directions.....	4
7. Matters required attention.....	4
8.Services.....	4

1. Brief Introduction

The technology parameter of PCE-GM 100 Glossmeter is complete according with state standard GB9754-88 GB9966.5 and international standard ISO2813, all items of the performance meet the first class work requirements of state JJG696-2002 (Lens Luster Degree Instrument Measure Test Regulations) .

2. Applications

The surface luster measure for printing ink, paint, bake lacquer, coating and woodwork
The surface luster measure for construction decoration materials: marble; granite; glass
chemical polishing brick and pottery brick
The surface luster measure for plastic and sheet
The surface luster measure for other non-metal materials

3. Instrument Characteristics

Fine, light stylish appearance, easy to carry
Completely intelligitized design, single key operation, convenient to use
Automatic adjustment, no need to be hand adjustment
Multi-angles, choose what you want
Long life-span lamp- house, no need to change
Precise measure, excellent repetition performance
LCD digital display
There is buzz sound during operation
Have electrical source pressure shortage indication function
Turn off automatically

4. Technology parameter

Measure range: 0-200GU
Stability: $<\pm 0.4$ GU/30Min
Value error: $<\pm 1.2$ GU
Power: 1.5V
Projecting angle: 20°60°85°
Environment temperature: 0-40
Relative humidity: $\leq 85\%$
Standard panel dimension: 95×40mm

5. Display instructions

“GU”--- luster unit
“CAL OK?”--- adjustment prompt
2: ???----the luster value of 20°
6: ???----the luster value of 60°
8: ???----the luster value of 85°
“Battery Low ”--- low battery voltage, prompt to change battery

6. Directions

(1). Press the red **POWER** key to start the gauge, and "CAL?" is displaying in the screen, make the gauge measure-window pointing at the black quartz crystal standard board, press the yellow **OP** key to confirm adjustment operation, when "CAL OK" display the screen, the gauge adjustment finished, and then press yellow OP key to measure the black quartz crystal standard board, if the reading on the screen is correct, the adjustment is valid.

(2). After finishing adjustment operation, the gauge is entering into the measure state. Put the gauge on the measured sample, appoint the measure window to the measured object, press the yellow **OP** key, the gauge starts to measure, the luster value of the measured object will display on the screen while there is buzz sound, (**2: ???**----the luster value of 20°; **6: ???**----the luster value of 60°; **8: ???**----the luster value of 85°).

please note that the measured object should be leveled off;

(5). The gauge can be turned off with hand, press **POWER** key, it is in the close state, there is nothing displaying on the screen; if there is no measure operation in the gauge for 3 minutes, it will turn off automatically.

7. Matters required attention

(1). It should avoid strong light direct radiation; or it will affect the measure precision.

(2). The standard panel of the gauge should be kept clean, please do not touch the surface with fingers. If there is dirt on the surface, the measure precision will be affected. Wipe it with lens cloth or absolute alcohol.

(3). When the battery is running out, the gauge will display **Battery low** on the screen, which needs to change battery. Open the battery cover, replace the old battery with the new one, please pay attention to the joint line polarity. The battery should be changed when it runs up, otherwise, it stored for a long time may flow the liquid which cause damage of the instrument. It should be taken out and keep proper if it is not used for a long time.

8.Services

This instrument has one-year quality guarantee, maintenance for all life. If there are any problem of this product, please contact the dealer in time.

In this direction will find a vision of the measurement technique:

www.pce-instruments.com

NOTE: "This instrument doesn't have ATEX protection, so it should not be used in potentially explosive atmospheres (powder, flammable gases)."