

## **Thickness Gauge PCE-CT 5000H**







## PCE-CT 5000H Thickness Gauge

## Non-destructive coating and dry film thickness (DFT) measuring device for use on ferrous (Type F) and non-ferrous (Type N) metal substrates

PCE-CT 5000H is a thickness measuring instrument used for the rapid determination of coating thicknesses on ferrous (Type F) and non-ferrous (Type N) metals. The coating thickness gauge automatically detects the type of metal to be measured. The PCE-CT 5000H coating thickness gauge uses magnetic induction (ferrous) or eddy current (non-ferrous) to take non-destructive measurements of coating and dry film thickness (DFT) on metal substrates such as steel and aluminum.

This thickness gauge is ideal for painted and powder-coated surface testing, automotive paint inspection, coated material testing, and manufacturing quality control applications. Alarm limits can be set in the coating thickness gauge to notify the user when a coating is too thick or too thin. If a coating thickness measurement falls outside the established limits, a message appears on the display to alert the user.

- Designed for non-destructive testing and inspection
- Measures coating thickness on Fe and nFe metals
- Displays measuring units in μm, mm or mils
- Saves up to 2000 measurements to internal memory
- Practical V-groove on the measuring head
- One- to four-point and zero calibration
- Comfortable one-handed operation
- Programmable alarm limits
- High measuring range
- High measuring accuracy
- Automatic shutdown

> Optional ISO calibration certificate available for purchase separately - see accessories tab for details

Subject to change



www.pce-instruments.com

## **Specifications**

Probe

Type F and Type N

Measuring range Type F
Measuring accuracy Type F
Resolution Type F

Measuring principle Type F Smallest thickness of the base material

Measuring range Type N Measuring accuracy Type N Resolution Type N

Measuring principle Type N Smallest thickness of the base material

Calibration
-------------

Data storage

Measurement units

Alarm

Power supply

Minimum radius of curvature (convex) Minimum radius of curvature (concave) Smallest measuring surface Maximum measuring rate Data interface Data transfer via USB

0 ... 5000 µm / 0 ... 5 mm / 0 ... 196 mils  $\pm (2\% + 1 \,\mu m)$ 0 ... 99.9 μm: 0.1 μm, 100 ... 999 μm: 1 μm > 1000 µm: 0.01 mm Magnetic induction 0.02 mm

0 ... 3000 µm / 0 ... 3 mm / 0 ... 118 mils ± (2% + 1 μm) 0 ... 99.9 μm: 0.1 μm, 100 ... 999 μm: 1 μm > 1000 µm: 0.01 mm Eddy current 0.05 mm

One-point to four-point calibration, zero calibration Direct measurement (no measurement data storage), four data groups (automatic measurement data storage of up to 2000 measured values) Statistical functions Number of measurements, average, minimum, maximum, standard deviation μm, mm, mils Alarm limits adjustable, alarm symbol is displayed when limits are exceeded 5 mm / 0.2 in 25 mm / 1 in Diameter of 20 mm / 0.8 in 2 x per second

2 x 1.5V AAA batteries

More information



Menu languages	German, English, Russian, Chinese
Operating conditions	0 50°C / 32 122°F, 20 90% RH
Storage conditions	-10 60°C / 14 140°F
Standards	CE ROHS FCC
Dimensions	110 x 53 x 24 mm / 4.33 x 2.09 x 0.95 in
Material housing	ABS plastic
Weight	92 g / < 1 lb

Subject to change



www.pce-instruments.com