

Technical Specification Air Humidity Meter PCE-TH 5

- For temperature and humidity
- Data-Hold function
- Internal sensor
- Min, Max and Average function
- Battery saving function
- Dew point and wet bulb temperature

Technical data for the Air Humidity Meter PCE-TH 5

Temperature measuring range	-20 ... +50 °C
Resolution	0.1 °C
Accuracy	±0.6 °C
Humidity measuring range	0 ... 99.9% r.H.
Resolution	0.1% r.H.
Accuracy	±3% (25 °C, 10 ... 90%), otherwise 5% r.H.
Operating temperature	-20 ... +50 °C, <80 % r.H.
Power supply	CR2032 lithium battery
Dimensions	135 x 18 x 36.3 mm