Thermometer PCE-T 330-ICA incl. ISO Calibration Certificate







Two-channel thermometer / Battery life of approx. 190 hours / Different file formats / No software required / Storage for 20,000 data points

The thermometer has two measuring inputs. Each measuring input from the thermometer can be connected to a thermocouple of type K, T and J. With a measuring rate of 2 Hz, the thermometer shows rapid temperature fluctuations. With the high accuracy and a resolution of 0.01 °C, these rapid temperature fluctuations can also be displayed precisely by the thermometer.

With a data memory of 20,000 measuring points, the thermometer can be used for a long period of time. A data point on the thermometer contains a measured value per channel and date as well as the current time. When the thermometer is connected to a computer, it is recognized as a removable disk. This allows the thermometer to be connected to computers with different operating systems, as no additional software is required for further analysis. The measurement data from the thermometer can be saved as TXT, CSV, XLS and DLG format.

- Two-channel temperature data logger
 - For thermocouples type K, T and J
 - Long battery life
- Data storage for 20,000 measuring points
 - File format TXT, CSV, XLS and DLG
 - ▶ Rubberized protective cover
 - incl. ISO Calibration Certificate





www.pce-instruments.com

Specifications

Temperature	Measuring range	Resolution	Accuracy
Sensor			
Туре К	-200 1370 °C / -328 +2498 °F	0.01 °C	±0.3 % of rdg. +0.4 °C
Туре Т	-200 400 °C / -328 752 °F	0.01 °C	±0.3 % of rdg. +0.4 °C
Туре Ј	-200 1200 °C / -328 2192 °F	0.01 °C	±0.3 % of rdg. +0.4 °C
Units		°C / °F	
Number of channels		2	
Measuring rate		2 Hz	
Data storage		15,328 kB for 20,000 data points	
File formats		TXT, CSV, XLS, DLG	
Storage interval		1 86,399 s	
Interface		Micro-USB	
Power supply		3 x 1.2 V AAA rechargeable	
		batteries	
		3 x 1.5 V AAA batteries	
Battery life		ca. 190 hours	
		(without backlight, battery capacity	
		1200 mAh, ambient temperature 25	
		°C)	
Operating conditions		-10 50 °C / 14 122 °F	
Storage conditions		-20 60 °C / -4 +140 °F (without	
		batteries)	
Dimensions		173 x 71 x 38 mm / 6.8 x 2.8 x 1.5"	
Weight		ca. 226 g / 7.9 oz	

More information







www.pce-instruments.com