

Crane Scale PCE-CSI 15



Crane Scale Weighing range 15 t / Control via remote control / Display with 75 mm digit height Hold, tare and totalizing function / Integrated 7 Ah battery / Operating time ≥ 40 h

The crane scale was developed for in-house weighing of up to 15 t. The crane scale has a massive shackle on the top and a rotatable hook with a safety catch on the underside. The crane scale is operated using the infrared remote control supplied. The 5-digit LED display has a digit height of approx. 75 mm, so that the readings can be read from a distance without any problems. The integrated battery of the crane scale ensures an operating time of over 40 hours. The battery level can be checked at any time. If it is low, the display of the crane scale also starts to flash, so that it is easy for the operator to see when the battery needs to be charged.

The crane scale also offers other useful functions. The tare function enables weights to be tared (e.g. slings such as ropes, chains, etc.). If the weight of the objects to be tared is known, this can also be entered manually in advance. Another useful function of the crane scale is the totalizing function. Several weights can be added and the sum read out. The display hold function can also be used to freeze measured values on the display.

- Weighing range: 15,000 kg / 33,069 lb
- Resolution: 5 kg / 11 lb
- Minimum load: 100 kg / 220 lb
- Control via remote control
- Up to 40 hours of operation
- Tare, hold and totaling functions
- 5-digit display with 75 mm / 2.9" digit height
- Easy handling





www.pce-instruments.com

Specifications

| Weighing range | 15,000 kg / 33,069 lb |
|-----------------------------|--|
| Minimum load | 100 kg / 220 lb |
| Resolution | 5 kg / 11 lb |
| Standards | OIML class III |
| Zero range | 4 % of the weighing range |
| Tare range | 100 % of the weighing range |
| Settling time | ≤ 10 seconds |
| Overload display | 100 % of the weighing range + 9e |
| Max. safety load | 125 % of the weighing range |
| Maximum load | 400 % of the weighing range |
| Display | 5-digit LCD/LED, 75 mm / 2.9" digit height |
| Battery | fully sealed lead battery, 6 V / 7 Ah |
| Operating time | ≥ 40 hours |
| Power supply | 9 V DC / 1000 mA |
| Remote control range | 15 m / 49 ft |
| Power supply remote control | 2 x 1.5 V AAA batteries |
| Operating temperature | -20 °C to 70 °C / -4 °F to 158 °F |
| Operating humidity | \leq 85 % RH at below +20 °C / 68 °F |
| Weight | 44 kg / 97 lb |
| Dimensions | |
| Α | 1050 mm / 41.3" |
| В | 360 mm / 14.1" |
| C | 635 mm / 25.0" |
| D | 775 mm / 30.5" |

More information







www.pce-instruments.com