

Manometer PCE-PDA A100L







PCE-PDA A100L Manometer

Measuring instrument for barometric absolute pressure up to 200 kPa / Data logger / Graphic LCD / With USB interface / MAX MIN HOLD function

The manometer PCE-PDA A100L is suitable for the measurement of the atmospheric pressure. This manometer records the pressure from absolute zero to 200 kPa. The manometer can be used for many mobile applications in industry and crafts. This professional manometer can either be operated with batteries or rechargeable batteries. In battery mode, the USB interface allows charging of the inserted batteries. The PCE-PDA A100L manometer is equipped with a large LC display. A display illumination makes it easier to read the measured values even under poor conditions. The pressure is measured by an internally installed sensor.

A plug-in nipple is available from the pressure connection. At these, the pressure of air and liquids can be passed through quick couplings to the sensor. The manometer has a precision mode that allows the resolution of the measured value to be increased tenfold. In addition to the continuous pressure measurement, the display shows the maximum and minimum measured values directly in the display. At the touch of a button, this storage can be reset. Furthermore, the manometer performs a temperature measurement. To store the measured values for further documentation purposes, the manometer has a data logger. Here, the user can specify a storage interval and a recording period in which the pressure measured values are stored.

- ► Graphic LCD
- ▶ USB interface
- Datalogger
- Absolute pressure measurement
- ▶ Different units
- ► MAX MIN HOLD function
- ► Measured value smoothing
- Integrated temperature measurement

Subject to change

Specifications

Measuring range pressure 0 ... 200 kPa absolute
Resolution 0.01 kPa, 0.1 kPa

Accuracy <± 0.5% of the measuring range

Nominal pressure 200 kPa
Overpressure 200 kPa
Burst pressure 300 kPa

Media Liquids

Air

Non-aggressive gasses

Measuring rate 10 Hz

Measurement units Pa, hPa, kPa, MPa, mbar, bar, ATM, kg / cm²,

mmH2O, cmH2O, inH2O, mmHg, inHg, Torr,

PSI, PSF

Pressure Absolute pressure

Pressure connections 5 mm nipple for quick connectors

Max, Min and Hold function Yes

Data logger 1024 memory slots

1 s ... 255 h Recording time per memory

location

1 s ... 24h recording interval

Medium For air and non-explosive gasses

Zero correction Yes, with a zero key

Averaging Yes, between 0.1 ... 9.9 s

Display Graphic LCD with backlight

Protection IP41

Power supply 2 x 1.5V AA battery / 1.2V NiMh battery

5V / 500-mA USB power adapter

Current consumption 50-mA (with backlight)

10-mA (without backlight)

Operating temperature $0 \dots 50^{\circ}\text{C} / 32 \dots 122^{\circ}\text{F}$ Storage temperature $10 \dots 55^{\circ}\text{C} / 50 \dots 131^{\circ}\text{F}$

Dimensions 145 x 85 x 35 mm / 5.7 x 3.3 x 1.4 in

Weight About 285 g / < 1 lb

More information

Manual

<u>...</u>

More product info



Similar products

