

Clamp Meter PCE-PCM 3







Clamp meter PCE-PCM 3

Digital multimeter for single-phase measurement / NCV measurement / W / VA / Var /Inrush Current / 1000 A AC Current Measurement / Bluetooth Interface / Frequency Measurement / Backlight / Voltage measurement / 750 kW power

With the digital multimeter AC currents of up to 1000 A AC can be measured easily. At the same time, voltages of up to 1000V AC / DC can be measured with the digital multimeter. Thus, with the power current clamp, apparent power, reactive power and active power measurements up to 750 KW are possible. Another function of the digital multimeter is the measurement of the inrush current. Many consumers have a tremendously high current at the moment of switch-on. With a conventional digital multimeter such a measurement is not possible. For the digital multimeter this is not a problem.

With the NCV (Not Connected Voltage) function of the digital multimeter, it can be checked whether a voltage is applied to a line without performing a contacting measurement. This makes the work much easier for the user thanks to the digital multimeter. In addition to the measuring function, the digital multimeter can also be connected to a terminal via the Bluetooth interface. Via this Bluetooth interface, the measured data can be transmitted directly from the digital multimeter to the terminal, where it can be logged, analyzed and sent.

- Apparent / active / reactive power
- ▶ Measurement up to the 20th harmonic
- "Not Connected Voltage" function
- ▶ Inrush current measurement
- ▶ Current measurement up to 1000 A AC
- ▶ Bluetooth interface

Specifications

Ambient conditions 23° C / 73.4° F \pm 5° C / 41° F, < 75% RH

Measuring function

Current measurement AC

Measuring range	Resolution	Accuracy
60 A	0.01 A	± 2% + 8 Dgt
600 A	0.1 A	± 2% + 8 Dgt
1000 A	1 A	± 2% + 8 Dgt

Maximum input current: 1000 A AC Frequency range: 40 400 Hz

Measuring function

Inrush current AC

Measuring range	Resolution	Accuracy
60 A	0.01 A	For reference only
600 A	0.1 A	± 5% + 60 Dgt
1000 A	1 A	± 5% + 60 Dat

Integral time: 100 ms

Measuring range: 20 ... 1000 A Frequency range: 40 400 Hz

Measuring function

Voltage measurement DC

Measuring range	Resolution	Accuracy
6V	0.001V	± 0.5% + 5 Dgt
60V	0.01V	± 0.5% + 5 Dgt
600V	0.1V	± 0.5% + 5 Dgt
1000V	1V	± 0.8% + 4 Dgt

Input impedance: $10 \text{ M}\Omega$

Maximum input voltage: 750V AC (rms value) or 1000V DC

Measuring function

Voltage measurement AC

Measuring range	Resolution	Accuracy
6V	0.001V	± 0.6% + 4 Dgt
60V	0.01V	± 0.6% + 4 Dgt
600V	0.1V	± 0.6% + 4 Dgt
1000V	1V	± 0.8% + 4 Dgt

Input impedance: $10 \text{ M}\Omega$

Maximum input voltage: 750V AC (rms value) or 1000V DC

Frequency range: 40 ... 400 Hz

More information

Manual

More product info



Similar products



Measuring function

Frequency measurement with

The current measuring function

Measuring range	Resolution	Accuracy
99.99 Hz	0.01 Hz	± 1.5% + 5 Dgt
999.9 Hz	0.1 Hz	± 1.5% + 5 Dgt

Measuring range: 10 ... 1 kHz

Measuring range of the input signal: > 20 AAC (rms value)

The input current increases with the measuring frequency.

Maximum input current: 1000 AAC (rms value)

Measuring function

Frequency measurement with the

Voltage measurement function

Measuring range	Resolution	Accuracy
99.99 Hz	0.01 Hz	± 1.5% + 5 Dgt
999.9 Hz	0.1 Hz	± 1.5% + 5 Dgt
9,999 kHz	0.001 kHz	± 1.5% + 5 Dgt

Measuring range: 10 ... 10 kHz

Measuring range of the input signal: > 1V AC (rms value)

The input current increases with the measuring frequency.

Maximum input voltage: 1000V AC (rms value)

Measuring function

Frequency measurement

Measuring range	Resolution	Accuracy
9,999 Hz	0.001 Hz	± 0.3% + 5 Dgt
99.99 Hz	0.01 Hz	± 0.3% + 5 Dgt
9,999 kHz	0.1 Hz	± 0.3% + 5 Dgt
999.9 Hz	0.001 kHz	± 0.3% + 5 Dgt
99.99 kHz	0.01 kHz	± 0.3% + 5 Dgt
999.9 kHz	0.1 kHz	± 0.3% + 5 Dgt
9,999 MHz	0.001 MHz	± 0.3% + 5 Dgt

Overvoltage protection: 1000V DC or 750V AC (rms value)

Range of voltage input> 2V

(as the input voltage increases, so does the frequency)

Measuring function

Duty cycle

Measuring range	Resolution	Accuracy
0.1 99.9%	0.1%	+ 0.3% + 5 Dat

Frequency range: 10 ... 10 kHz

Voltage range: 2 ... 250V AC (rms value)
(The voltage increases with the frequency)

Duty cycle with the Frequency range: 10 ... 1 kHz

Current measurement function Input current: 20 ... 1000 AAC (rms value)



Duty cycle with the Frequency range: 10 ... 1 kHz

Voltage measurement function Input current: 1 ... 750V AC (rms value)

Input impedance: $1M\Omega$

Measuring function

Resistivity

Measuring range	Resolution	Accuracy
600 Ω	0.1 Ω	± 0.8% + 3 Dgt
6 kΩ	0.001 kΩ	± 0.8% + 3 Dgt
60 kΩ	0.01 kΩ	± 0.8% + 3 Dgt
600 kΩ	0.1 kΩ	± 0.8% + 3 Dgt
6 ΜΩ	0.001 ΜΩ	± 2% + 5 Dgt
60 ΜΩ	0.1 ΜΩ	± 2% + 5 Dat

Measuring voltage: approx. 0.78V

Overvoltage protection: 750V DC, 1000V AC (rms value)

Measuring function

Continuity test

Measuring range	Resolution	Accuracy
600 Ω	0.1 Ω	-

Acoustic signal at $< 50 \ \Omega$

Test voltage: 1.48V

Overvoltage protection: 750V DC, 1000V AC (rms value)

Measuring function

Capacitance measurement

Measuring range	Resolution	Accuracy
9.999 nF	0.001 nF	± 3% + 5 Dgt
99.99 n.f.	0.01 nF	± 3% + 5 Dgt
999.9 nF	0.1 nF	± 3% + 5 Dgt
9.999 μF	0.001 μF	± 3% + 5 Dgt
99.99 μF	0.01 μF	± 3% + 5 Dgt
999.9 μF	0.1 μF	± 3% + 5 Dgt
9,999mF	0.001 mF	± 3% + 5 Dgt
99.99 mF	0.01 mF	± 3% + 5 Dgt

Overvoltage protection: 750V DC, 1000V AC (rms value)

Measuring function

Diode measurement

Measuring range	Resolution	Accuracy
3V	0.001V	-

DC anode side: approx. 1-mA DC cathode side: approx. 3.2V

Overvoltage protection: 750V DC, 1000V AC (rms value)



Measuring function

Single phase power measurement

Measuring range	Resolution	Accuracy
3 W / VA / Var	0.01 W / VA / Var	± 3% + 5 Dgt
100 W / VA / Var	0.1 W / VA / Var	± 3% + 5 Dgt
4000 W / VA / Var	1 W / VA / Var	± 3% + 5 Dgt
10 kW / VA / var	0.01 kW / VA / Var	± 3% + 5 Dgt
100 kW / VA / var	0.1 kW / VA / Var	± 3% + 5 Dgt
750 kW / VA / var	1 kW / VA / Var	± 3% + 5 Dgt

Smallest measuring current: 1-mA Smallest measuring voltage: 1V

Measuring function

Power factor capacitive / inductive

Measuring range	Resolution	Accuracy
0.1 1	0.001	± 5% + 5 Dgt

Smallest measuring current: 1-mA Smallest measuring voltage: 1V

Measuring function

Harmonics measurement

Measuring range	Resolution	Accuracy
1	-	± 3% + 10 Dgt
2 6	-	± 3.5% + 10 Dgt
7 8	-	± 4.5% + 10 Dgt
9 10	-	± 5% + 10 Dgt
11 15	-	± 7% + 10 Dgt
16 20	-	± 10% + 10 Dgt

Smallest measuring current: 1-mA Smallest measuring voltage: 1V

The resolution depends on the voltage measuring range

General specifications

Measuring range Automatically and manually adjustable	Measuring range	Automatically and manually adjustable
---	-----------------	---------------------------------------

Maximum voltage range	1000V DC or 750V AC
Maximum working height	2000 m / 6561 ft

Display	LCD
Maximum display	5999 Dgt.
Overrange	"OIL"
Measuring range underflow	"-OL"
Measuring rate	3 Hz

Automatic shutdown After 30 minutes

Power supply 9V block battery

Battery indicator Icon if the battery voltage is too low

Temperature coefficient $0.1 \times accuracy \times °C / °F*$ Operating conditions $0 \dots 40 °C, 32 \dots 104 °F$ Storage conditions $-10 \dots 60 °C, 14 \dots 140 °F$

Dimensions 238 x 92 x 50 mm / 9.4 x 3.6 x 2 in



Accuracies are given at ambient conditions of 18 ... 28°C / 65 ... 83°F.

*The temperature is the difference between the temperature of the operating conditions and the current ambient temperature.

Example:

Is the current ambient temperature greater than the temperature of the operating conditions

(50°C / 122°F (current ambient temperature)) - (40°C / 104°F (operating temperature)

= 10°C / 50°F

Is the current ambient temperature less than the temperature of the operating conditions

(0°C (operating temperature)) - (-5°C / 23°F (current ambient temperature))

 $= 5^{\circ}C / 41^{\circ}F$