



PCE Americas Inc.  
711 Commerce Way  
Suite 8  
Jupiter  
FL-33458  
USA  
From outside US: +1  
Tel: (561) 320-9162  
Fax: (561) 320-9176  
info@pce-americas.com

PCE Instruments UK Ltd.  
Units 12/13  
Southpoint Business Park  
Ensign way  
Hampshire / Southampton  
United Kingdom, SO31 4RF  
From outside UK: +44  
Tel: (0) 2380 98703 0  
Fax: (0) 2380 98703 9  
info@pce-instruments.com

[www.pce-instruments.com/english](http://www.pce-instruments.com/english)  
[www.pce-instruments.com](http://www.pce-instruments.com)

## Datasheet Moisture Analyser GMH 3850

- Moisture meter for measuring weight humidity
- 466 characteristic curves for sorts of wood
- 28 characteristic curves for sorts of construction materials
- Humidity estimation in 9 steps
- Connection of an external NiCr-Ni (Type K) temperature probe
- Serial interface
- Analog output 0-1V, free scaleable
- incl. calibration protocol

### Technical Data

Measuring Range Moisture	0,0 ... 100,0% weight humidity
Measuring Range Temperature	-40,0 ... 200,0 °C
Sensor Connection	BNC (humidity) and NiCr-Ni jack (temperature)
Working Temperature	-25 ... +50 °C
Power Supply	9V battery, IEC 6F22