

Technical Airflow Meter PCE-KWR 1

Wind Sensor PCE-KWR 1

Basic wind direction sensor with potentiometer output /

Wind direction sensor PCE-KWR1 for example for PCE-WL wind logger. Basic wind direction sensor with potentiometer output.

- Basic wind direction sensor
- 3 m connection cable
- Easy assembly
- Compatible with PCE-WL1 and PCE-WL2

Technical Datas

Output	0 ... 1000 Ohm
Measurement reading range	10 ... 350 °
Accuracy	± 5 °
Start-up Load	1 m/s at 90°
Contact Load	0,3 W max 1 mA
Assembly	mounting bracket
Ambient temperature	25 ... +60 °C (in ice-free conditions)
Cable (selectable)	3 m; LiYY 4 x 0,5 mm ²
Protection class	IP54
Weight	ca. 300g

Delivery content

1 x PCE-KWS1, 1 x Data sheet